

DJ503226


Computer DesK

Installation Option I




Installation Option II








GAUTION: When tightening the screws, tighten sequentially. Do not tighten any screws fully and then towards the next one. When every part is OK, then tighten all the screws




Α	x8	В	x12+1	C	x8	D	x2	E	x1	F	X ²
								0	8	-0000GB)	
		M6x35		M5X38						ST3x16	
Н	x2	I	x20+1	J	x2	K	x1	L	X13+1		
		M6X25		ST3.5x12				M6X28			
М	x8	N	х3	0	x1	Р	x4	T	x1		
(M)		J.									
M6									2		









Step 5 11 Step 6




Installation Option I





With the basic components of Step1-step6, the following installation method is the first.


















Installation Option II



With the basic components of Step1-step6, the following installation method is the Second

