












INSTRUCTION MANUAL




■ Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.

■ If you have any question, please feel free to contact us.




				 M5x50mm	 M6x10mm
① X4	② X4	③ X4	④ X17	A X68	B X18
 M3x1 M4x1					
C X1	D X2	E X8	F X2		


- B X8
- E X8
- ① X4
- ② X4




A X48
④ X12




A X20
④ X5



B X10
D X2
3 X4



F X2



F X2

